







While assembling the smith machine it is very important, that while placing the linear bearing covering the on rod (B). You do so as straight as possible. Failing to do so may cause damage to the linear bearings.

